



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

DOT Auto Safety Hotline
Vehicle Owner's Questionnaire
To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100186

Date Received
24-SEP-2003
Repository
Reference No.
10040580

OWNER INFORMATION (Type or Print)

Name
Address
City WASHINGTON State DC Zip Code
Daytime Telephone Number E-mail Address
Evening Telephone Number

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.
Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side
9999 Make DATSUN Model DATSUN Model Year 1978
Date Purchased Dealer's Name and Telephone Number NISSAN DATSUN MOTOR CORPORATION Engine: No: Cylinders Fuel Type:
Original Owner Dealer's City CARSON State CA Zip Code 90245
Transmission Type Antilock Brakes Powertrain Vehicle Component Code 012200 STEERING:COLUMN LOCKING:ANTI-THEFT DEVICE
 Cruise Control Multiple Failure: 7

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s) 01-JAN-1901 Failure Mileage Failure Speed

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make Tire Model (Name or Number) Tire Size (Example P215/65R15)
DOT No. (Example: DOTM19ABC036) Original Equipment Failure Location:
 Prior Repair
Tire Component Code Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make: Date Manufactured: Model No./Name:
Seat Type: Installation System:
Child Seat Component Code: Failed Part:

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury (ies).)

Crash Yes No Fire Yes No Number of Persons Injured Number of Deaths Reported to Police N

Narrative Description of Incident(S), Crash(es), and Injury (ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e. parts repaired or replaced (and if old part is available).

STEERING LOCK UP'S OCCURING ON 1978-1980 DATSUNS.*MR *CB

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.